



MAINTENANCE INSTRUCTIONS

CODE: MRSB/RAT1 – MILLENNIUM RATCHET SEAT BACK

Visual Inspection

Check for excessive fraying of webbing belts (A and B)

- A. Orange webbing with karabiners
- B. Seat belt webbing (2 off) and extension belts (2 off)

Check that there are no nuts and bolts missing or damaged parts. In particular check that the seat belt buckles are not cracked.

Check that the unit or vehicle has the appropriate user instruction sheets.

Quarterly mechanical workshop check

Check the unit fits into and locks into the tracking correctly. Check this in two positions – storage position at the rear of the vehicle and in its used position.

Check the ratchet is securely fitted onto the base.

Check that the ratchet mechanism is working correctly.

Check all the nuts and bolts on the millennium fittings are tight.

Check that the seat belts lock into the buckles and retract correctly.

Check that the seat trim is not torn.

For further information please consult the following NMI documents:

MRSB/RAT user instruction sheets

Spare parts should be ordered from NMI Safety Systems Ltd only.

T – 0044 208 801 5339/5512

E – sales@nmisafety.com

www.nmisafety.com

Sept 2006

